

	Type	Hits	Search Text	DBs
1	IS&R	1	("4600425").PN.	USPAT
2	BRS	0	((tube near5 (bubbler or bubble) near5 gas) near50 ((cool or cooling or water\$1cooling) near3 jacket)) near350 (metal or platinum)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
3	BRS	2	((tube near5 (bubbler or bubble) near5 gas) near50 ((cool or cooling or water\$1cooling) near3 jacket))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
4	BRS	0	(platinum near25 (lining or liner) near25 tube near50 (corrosion near5 resist\$4))	USPAT
5	BRS	0	(platinum near25 (lining or liner or line) near25 tube near50 (corrosion near5 resist\$4))	USPAT
6	BRS	0	(platinum near25 (lining or liner or line) near25 tube near50 (corrosion near5 resist\$4))	USPAT
7	BRS	11	(platinum near25 (lining or liner or line) near50 (corrosion near5 resist\$4))	USPAT
8	BRS	4	(platinum near50 (polytetrafluoroethylene or PTFE) near50 (corrosion near5 resist\$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
9	BRS	2	(platinum near50 (polytetrafluoroethylene or PTFE) near50 (corrosion near5 resist\$4))	USOCR
10	BRS	2	(platinum near50 (polytetrafluoroethylene or PTFE or teflon) near50 (corrosion near5 resist\$4))	USOCR
11	BRS	10	(platinum near50 (polytetrafluoroethylene or PTFE or teflon) near50 (corrosion near5 resist\$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
12	BRS	162	(platinum near50 (stainless adj steel) near50 (corrosion near5 resist\$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
13	BRS	4	((platinum near5 (layer or lining)) near50 (stainless adj steel) near50 (corrosion near5 resist\$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB